

J1939 Router

Release Notes

A-J1939

Document No. D123-009

Document Revision 1.0

08/2022

Firmware Revision 1.006

CONTENTS

1. Preface.....	2
1.1. Compatibility.....	2
1.2. Notes.....	2
1.3. Additional Information.....	2
1.4. Support.....	3
2. Improvements.....	3
3. Anomalies Fixed.....	3
4. Known Anomalies.....	3



1. PREFACE

1.1. COMPATIBILITY

Firmware revision 1.006 of the J1939 Router will require the following compatible versions:

Software	Version
Slate	1.061 and later

1.2. NOTES

The following should be noted:

- Firmware upgrades will be done using Aparian's Slate software.
- Aparian flash files have an *.afb* extension.
- Slate can also be used to set the initial network parameters using its DHCP server.
- Should any interruptions cause the module to not complete the firmware upgrade the module will return to Safe Mode. The user can then re-flash the module with the application firmware. See the user manual for more information regarding Safe Mode.

1.3. ADDITIONAL INFORMATION

The following resources contain additional information that can assist the user with the module installation and operation.

Resource	Link
Slate Installation	http://www.aparian.com/software/slate
J1939 Router User Manual J1939 Router Datasheet Example Code & UDTs	http://www.aparian.com/products/j1939router
Ethernet wiring standard	www.cisco.com/c/en/us/td/docs/video/cds/cde/cde205_220_420/installation/guide/cde205_220_420_hig/Connectors.html
SAE J1939 Standards	http://www.sae.org/standardsdev/groundvehicle/j1939a.htm

1.4. SUPPORT

Technical support will be provided via the Web (in the form of user manuals, FAQ, datasheets etc.) to assist with installation, operation, and diagnostics.

For additional support the user can use either of the following:

Contact Us web link	www.aparian.com/contact-us
Support email	support@aparian.com

2. IMPROVEMENTS

The following updates are included in this firmware revision.

Revision	Improvement	Description
1.006	General	Non-application specific update.
1.005	J1939 Ack	Added option for ACK requirement in the mapping.
	Remote Node	Added remote node naming in mapping as well as hiding of remote node option for produce broadcast PGN as it was not used.
1.004	ODVA	Update to meet the latest ODVA conformance testing.
1.003	Enhancements	Minor enhancements and stability improvements to the EtherNet/IP stack.

3. ANOMALIES FIXED

The following anomalies have been fixed in this firmware revision.

Revision	Anomaly	Description
1.006	None	-
1.003	DIP Switch	Fixed reading of DIP switches for production testing.

4. KNOWN ANOMALIES

The following known anomalies exist in this firmware revision.

Revision	Anomaly	Description
1.006	None	-